





FIG. 1











STORAGE DEVICE


67978 U.S. PTO 08/815399 03/10/97




F1G. 5













67978 U.S. PTO 08/815399


















67978 U.S. PTO 08/815399



67978 U.S. PTO 08/815399






FIG. 9B


08/815399 08/10/97



BY CLASS SUBCLASS
DRAFTSMAN













FIG. 12(1)









FIG. 12(5)






FIG. 12(2)



